



GIN

Soft Shackle

pilot manual

v1.1, 09/2014






Pass the Soft Shackle line through the connections
2 TIMES

Pass the loop end of the line through the eyelet at the base of the black webbing

Pass the black webbing through the loop end

Pull tight on the black webbing to make a clean knot and fold onto the Velcro



Wrap the Velcro around one side of the line

Tape both ends of the attachment firmly to ensure the shackle does not move

Cover the Soft Shackle attachment using the Maillon rapid cover

DANGER: Failure to follow these procedures exactly may cause catastrophic failure

IMPORTANT: GIN recommends using the rapid cover however tape may also be used if done correctly

Certified: EAPR-BT-0274/14
25,737N, 2,624kg
Weight: 8g