



GIN




Soft Shackle User Manual

1



Make a small loop

2



Place the elastic onto the rescue bridle. Pass the soft shackle through the connectors.

3



Pass the soft shackle through the connectors a second time. Place rubber-band on knotted end.

4



Pass the knotted end through the small loop.

5



Pull tight to close the loop around the knot.

6



Make one twist in the rubber-band and pass it over the knotted end.

7



Tape the connectors and slide on the elastic.

WARNING: If not connected correctly the Soft Shackle may fail.

IMPORTANT: The Soft Shackle must be held in place to prevent excess friction.

NOTE: It is the pilot's responsibility to check compatibility and proper installation.

Max Breaking Load: 26,700 N (2722kg)

v.2.1, 04/2015